

TABULATED GEOHAZARD SUSCEPTIBILITY ASSESSMENT OF THE BARANGAY CENTERS WITHIN THE MUNICIPALITY OF TAMPILISAN, ZAMBOANGA DEL NORTE

BRGY	MUNICIPALITY/ CITY	LONGITUDE	LATITUDE	LANDSLIDE SUSCEPTIBILITY RATING	FLOOD SUSCEPTIBILITY RATING	LANDSLIDE REMARKS/RECOMMENDATIONS	FLOOD REMARKS/RECOMMENDATIONS	AS OF	ASSESSED BY/DATA SOURCE
Balacbaan	TAMPILISAN	122.6788611	7.9114167	moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Banbanan	TAMPILISAN	122.6524167	7.9175000	moderate to high	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Observe for sunken and/or displace road surfaces; Observe for spring/seepage in areas that are not typically wet; Identify evacuation site; Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Barili	TAMPILISAN	122.6620556	8.0068333	moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Cabong	TAMPILISAN	122.6923333	7.9008056	moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Camul	TAMPILISAN	122.6372778	7.9561944	moderate to high	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Farmington	TAMPILISAN	122.6813333	7.9618611	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Galingon	TAMPILISAN	122.6763333	7.9295833	moderate to high	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Lawaan	TAMPILISAN	122.6420278	7.9907778	moderate to high	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Lumbayao	TAMPILISAN	122.6923889	8.0260000	moderate to high	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Observe for sunken and/or displace ground surfaces; Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO

Malila-t	TAMPILISAN	122.6645278	8.0347778	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Molos	TAMPILISAN	122.6957778	8.0176944	moderate to high	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Observe for sunken and/or displace ground surfaces; Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
New Dapitan	TAMPILISAN	122.6957222	7.9840556	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Poblacion (Tampilisan)	TAMPILISAN	122.6616944	7.9748333	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Sandayong	TAMPILISAN	122.7327778	7.9367500	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Santo Niño	TAMPILISAN	122.6928889	7.9979444	moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Situbo	TAMPILISAN	122.7159444	7.9515833	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Tilubog	TAMPILISAN	122.7125278	7.8975278	moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Tininggaan	TAMPILISAN	122.7159167	7.9211944	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Tubod	TAMPILISAN	122.6976111	7.9208333	low to moderate	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO
Znac	TAMPILISAN	122.6538611	7.9489167	low to moderate (brgy. center); High-sloping grounds	none to low	Observe and/or monitor for presence of landslides (tension cracks; soil creep); Observe for sunken and/or displace ground surfaces; observe for seeps in areas that are not typically wet; Activate BDCC	Address and/or improve storm water drainage network	2006	MGB-RO

